

Mach3 Minimum Requirements:

- 32-bit version of Windows 2000, Windows XP, Windows Vista, or Windows 7 Operating System
- 1Ghz CPU
- 512MB RAM
- Non-integrated Video Card with 32MB RAM
- Basic Computer Skills (ability to copy/rename files, browse directories, etc)
- Desktop PC (if using the Mach3 Parallel Port Driver - laptops are not supported because the power saving features of the chipsets disrupt the pulse Stream,A and USB parallel adaptors will *not*work.)

上記の和訳したもの

Mach3 最低条件：

- システムを操作している Windows 2000、Windows XP、Windows Vista または Windows7 の 32 ビット・バージョン
- 1Ghz CPU
- 512MB RAM
- 32MB RAM 付きの非統合的ビデオカード
- 基本的なコンピュータスキル（ファイルのコピー/名前変更、ディレクトリの閲覧など）
- デスクトップ P C（Mach3 平行ポートドライバを使用している場合、ノートパソコンは使用できませんチップセットの省電力機能がパルスを中断するため使用できない。ストリーム、A、および USB 平行アダプターは*動作しません*。

推奨 Mach3 パソコン最小システム

古いデスクトップパソコンから Mach3 を駆動する場合

CPU: Pentium III -1GHz 以上

Memory: 128MB 以上

HDD: 10MB 以上の空き

CRT 解像度:1024X768 ドット,グラフィックボードメモリ 32MB

対応 OS : Windows 2000, XP, Vista, 7 (32bit 版のみ)

平行ポート (プリンタポート) から Mach3 を駆動する。

ノートパソコンは使用できません。

最近のパソコンの USB から Mach3 を駆動する場合

対応 OS : Windows 7,8.1,10 (32&64bit 版)

USB2.0 以上。

CNC ソフト : Mach3 または UCCNC

デスクトップ、ノートパソコン共使用可能です。

※ 制御盤が、平行ポート (プリンタポート) の時は UC100 の USB 装置が必要になります。

※ 制御盤が、Mach3 の USB ブレイクアウトボード対応であれば、UC100 は必要無く、パソコンと直接 USB 接続で使用できます。